

STERLING



A one story, detached, frame building with metal roof, on stone foundation, containing two rooms, heated by stoves, the flues to which are of standard construction, lighted by electricity. This building is approximately 26' X 72' and is in poor condition, the walls appear to have buckled and the floor has dropped down slightly.

Estimated 100% insurable value \$750.00